


- 35.901.16
- 35.901.16 10
- 35.901.16 12
- 35.901.16 18
- 35.901.16 20
- 35.901.16 23
- 35.901.16 40

27.601.34



- 61.1802.47 Ø1.5 - 35.901.16
- 61.1802.45 Ø1.0 - 35.901.16 10
- 61.1802.46 Ø1.2 - 35.901.16 12
- 61.1802.48 Ø1.8 - 35.901.16 18
- 61.1802.55 Ø2.0 - 35.901.16 20
- 61.1802.68 Ø2.3 - 35.901.16 23
- 35.1802.56 Ø4.0 - 35.901.16 40

COME SI ORDINA / HOW TO ORDER  
Kit ricambio  
Spare parts kit **35.302.18**

DESCRIZIONE: LANCIA SPOT Ø15		N°revisione 05	Data revisione 28/07/2015
<b>Braglia</b> SRL I-42122 REGGIO EMILIA - ITALY - UE Email tecnico@braglia.it	Tel. +39 0522 340648 Fax. +39 0522 345025	DISEGNATO A.BRAGLIA	APPROVATO G.BRAGLIA
	Dis.N°/Codice <b>35.901.16</b>		