



- 35.901.16
- 35.901.16 10
- 35.901.16 12
- 35.901.16 18
- 35.901.16 20
- 35.901.16 23
- 35.901.16 40

- 61.1802.47 Ø1.5 - 35.901.16
- 61.1802.45 Ø1.0 - 35.901.16 10
- 61.1802.46 Ø1.2 - 35.901.16 12
- 61.1802.48 Ø1.8 - 35.901.16 18
- 61.1802.55 Ø2.0 - 35.901.16 20
- 61.1802.68 Ø2.3 - 35.901.16 23
- 35.1802.56 Ø4.0 - 35.901.16 40

Come si ordina/How to order  
 Kit riparazione-Cod. **35.302.18**  
 Repair kit-C/N.

|   |                       |     |                                    |
|---|-----------------------|-----|------------------------------------|
| Percorso file 3D: U:/Archivio/braglia/Esplosi/35.901.16.pkg       |                       |     |                                    |
| DENOMINAZIONE: <b>Lancia Spot</b>                                 |                       |     | N°revisione<br><b>02</b>           |
|   |                       |     | Data revisione:<br><b>23/12/09</b> |
| <b>Braglia</b> SRL<br>I-42029 Masone (REGGIO EMILIA)-ITALY-UE     | Tel. ++39 0522 340648 | STE | RTE                                |
|   | Fax. ++39 0522 345025 |     |                                    |
| Email: <a href="mailto:braglia@braglia.it">braglia@braglia.it</a> |                       |     | Dis.N°/Codice<br><b>35.901.16</b>  |